Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION Work Order Name: WO/50005DE2133/1 Work Order Type: Weatherization

Audit Name: Audit (16)

CLIENT INFORMATION

| Client Name: | STOTTS, LUE | Address: |
|--------------|-------------|----------|
| Client ID: | 50005DE2133 | |

Alt. Client ID:

CLIENT CONTACT INFORMATION

| STOTTS, LUE | (901) 465-9379 | Applicant/Person of | |
|-------------|----------------|---------------------|--|
| | | Record | |

AGENCY INFORMATION

Agency:Delta Human Resource AgencyAgency Phone:(901) 476-5226Address:P. O. Box 634Fax:(901) 476-5258

Agency Contact: Martin, Darrell L. Work Phone:

Cell Phone: (901) 262-8090

Email Address: DarrelllMartin@bellsouth.net

| Company Name & License Number: | |
|--------------------------------|--|
| Contractor's Signature: | |

COMMENT

Measures

| Measure 1 Crav | wl Space Door 28"x24" | | | Componen | ts | | 1 | Inspected |
|--|---------------------------------|----------------------|--------------|-----------------------|-------|-----|------------------|-----------------|
| Comment | | | | Estimated | 1 | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Other | Door Only- Material | Each | 1 | | | | | |
| 2 Labor | Labor | | 1 | | | | | |
| 3 Other | Unit- Material | Each | 1 | | | | | |
| 4 Labor | Labor | | 1 | | | | | |
| Other Detail | | | | | | 1 | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | | • | Sub Total: | |
| | | | | | | | | |
| Measure 2 Floo | or Patch in Kitchen 2'x6' | | | Componen | ts | | | Inspected |
| | or Patch in Kitchen 2'x6' | | | Componen Estimated | | | Actual | Inspected |
| Comment # Material / Labor | Description / Comment | Units | Qty | - | | Qty | | Inspected Total |
| Comment | Description / Comment | <i>Units</i> Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| Comment# Material / Labor1 Health and Safety Items | Description / Comment | | | Estimated | 1 | Qty | Actual | |
| Comment# Material / Labor1 Health and Safety Items | Description / Comment Equipment | Each | 1 | Estimated | 1 | Qty | Actual | |
| Comment# Material / Labor1 Health and Safety Items2 Labor | Description / Comment Equipment | Each | 1 | Estimated | 1 | Qty | Actual | |
| Comment# Material / Labor1 Health and Safety Items2 Labor | Description / Comment Equipment | Each | 1 | Estimated | 1 | | Actual Unit Cost | |
| Comment# Material / Labor1 Health and Safety Items2 Labor | Description / Comment Equipment | Each Hour | 1 | Estimated | 1 | | Actual | |
| Comment# Material / Labor1 Health and Safety Items2 Labor | Description / Comment Equipment | Each Hour | 1 | Estimated Unit Cost | 1 | | Actual Unit Cost | |
| # Material / Labor 1 Health and Safety Items 2 Labor Other Detail | Description / Comment Equipment | Each Hour | 1 | Estimated Unit Cost | 1 | | Actual Unit Cost | |

| | | all 3 Foundation Vents | 16"x9" | | Componen | ts | | | nspecte |
|-----|--|------------------------|----------|--------|--------------|-------|-----|------------|---------|
| آما | omment | | | | Estimated | | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Labor | Labor | | 1 | | | | | |
| 2 | Construction Materials/Hardwar e | Material | Each | 1 | | | | | |
| C | Other Detail | | | | | |] [| | |
| | | | | | | | | | |
| | | | | Mossur | e Sub Total: | |] | Sub Total: | |
| | Measure 4 Repl | ace Broken Pane WD# | 4 30"x12 | 1 | Componen | ts | | 1 | nspecte |
| | oo.nc | | | | Estimated | | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | | |
| | Windows | Material | Each | 1 | | | | Unit Cost | Total |
| 2 | Labor | | | | | | | Unit Cost | Total |
| | | Labor | | 1 | | | | Unit Cost | Total |
| C | Other Detail | Labor | | | | | | Unit Cost | Total |
| C | Other Detail | Labor | | | | | | Unit Cost | Total |
| | Other Detail | Labor | | 1 | e Sub Total: | | | Unit Cost | Total |

| | place Broken Pane WD# | 10 30" x1 | 2" | Componen | ts | | | Inspected |
|--|--------------------------------|---------------|----------------|---------------------|-------|------|------------------|-----------------|
| Comment | | | | Estimated | | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Windows | Material | Each | 1 | | | | | |
| 2 Labor | Labor | | 1 | | | | | |
| Other Detail | | | | | | 1 | | |
| | | | | | |] [] | | |
| | | | Measur | e Sub Total: | |] . | Sub Total: | |
| Field Notes: | | | | | | | | |
| | | | | | | | | |
| - | place Broken Pane WD# | 7 12"x 23 | " | Componen | | | | Inspected |
| Comment | | | | Estimated | | | Actual | |
| Comment # Material / Labor | Description / Comment | Units | Qty | • | | Qty | | Inspected Total |
| Comment # Material / Labor | | | | Estimated | | Qty | Actual | |
| # Material / Labor 1 Windows | Description / Comment | Units | Qty | Estimated | | Qty | Actual | |
| # Material / Labor 1 Windows | Description / Comment Material | Units | Qty 1 | Estimated | | Qty | Actual | |
| # Material / Labor Windows Labor | Description / Comment Material | Units | Qty 1 | Estimated | | Qty | Actual | |
| # Material / Labor Windows Labor | Description / Comment Material | Units | Qty 1 | Estimated | | Qty | Actual | |
| # Material / Labor Windows Labor | Description / Comment Material | Units Each | Qty 1 1 | Estimated | | | Actual | |
| # Material / Labor Windows Labor | Description / Comment Material | Units Each | Qty 1 1 | Estimated Unit Cost | | | Actual Unit Cost | |
| # Material / Labor 1 Windows 2 Labor Other Detail | Description / Comment Material | Units Each | Qty 1 1 | Estimated Unit Cost | | | Actual Unit Cost | |

| / | <i>Measure</i> 7 Rep | olace Water Lines on Wa | ater Heate | er | Componen | ts | | | Inspected |
|--------|---|---|----------------------|--------------|---------------------|----------|------|------------------|-----------------|
| C | omment | | | | | | | | |
| | | | | | Estimated | <u> </u> | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Miscellaneous Supplies | Material | Each | 1 | | | | | |
| 2 | Labor | Labor | | 1 | | | | | |
| 0 | ther Detail | | | | | | , | | |
| L | | | | | | | | | |
| | | | | | | |] | Sub Total: | |
| | | | | Measur | e Sub Total: | |] | Sub Total: | |
| | | | | | | | | | |
| | Measure 8 Infi | Itration Redctn | | | Componen | | | | Inspected |
| II Co | omment | | Unito | Otiv | Estimated | <u> </u> | Otiv | Actual | |
| II Co | | Itration Redctn Description / Comment Infiltration Reduction | <i>Units</i> Each | Qty 1 | - | | Qty | | Inspected |
| # 0 | omment Material / Labor Miscellaneous | Description / Comment | | | Estimated | <u> </u> | Qty | Actual | Inspected Total |
| # 0 | Material / Labor Miscellaneous Supplies | Description / Comment | | | Estimated | <u> </u> | Qty | Actual | |
| # 0 | Material / Labor Miscellaneous Supplies | Description / Comment | | | Estimated | <u> </u> | Qty | Actual | |
| # 0 | Material / Labor Miscellaneous Supplies | Description / Comment | | 1 | Estimated | <u> </u> | | Actual | |
| # 0 O | Material / Labor Miscellaneous Supplies | Description / Comment | | 1 | Estimated Unit Cost | <u> </u> | | Actual Unit Cost | |
| # 0 O | Material / Labor Miscellaneous Supplies | Description / Comment | | 1 | Estimated Unit Cost | <u> </u> | | Actual Unit Cost | |

| Measure 9 DV | VH Tank Insulation | | | Componen | ts | | | Inspected |
|--|--|-----------------------|-----------------|-----------------------|-------|-----|------------|-----------|
| Comment | | | | | | | | |
| | | | | Estimated | 1 | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| Hot Water Equipment | DHW Tank Insulation | Each | 1 | | | | | |
| 2 Labor | DHW Tank Insulation | Each | 1 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Moscur | e Sub Total: | | | Sub Total: | |
| Field Notes: | | | Weasur | c oub rotal. | | | | |
| Field Notes: | | | Measur | c dub rotui. | | | | |
| Field Notes: | | | <i>I</i> weasur | e dub Fotur. | | | | |
| Field Notes: | | | Weasur | e dub Potati. | | | | |
| | VH Pipe Insulation | | Weasur | Componen | ts | | | Inspected |
| Measure 10 DV | VH Pipe Insulation | | Measur | L | ts | | | Inspected |
| Measure 10 DV | VH Pipe Insulation | | Measur | L | | | Actual | Inspected |
| | VH Pipe Insulation Description / Comment | Units | Qty | Componen | | Qty | | Inspected |
| Measure 10 DV Comment # Material / Labor | · | | | Componen Estimated | 1 | Qty | Actual | |
| Measure 10 DV Comment # Material / Labor 1 Insulation | Description / Comment | Units | Qty | Componen Estimated | 1 | Qty | Actual | |
| Measure 10 DV Comment # Material / Labor 1 Insulation | Description / Comment DHW Pipe Insulation | Units Each | Qty 1 | Componen Estimated | 1 | Qty | Actual | |
| Measure 10 DV Comment # Material / Labor 1 Insulation 2 Labor | Description / Comment DHW Pipe Insulation | Units Each | Qty 1 | Componen Estimated | 1 | Qty | Actual | |
| Measure 10 DV Comment # Material / Labor 1 Insulation 2 Labor | Description / Comment DHW Pipe Insulation | Units Each | Qty 1 | Componen Estimated | 1 | Qty | Actual | |
| Measure 10 DV Comment # Material / Labor 1 Insulation 2 Labor | Description / Comment DHW Pipe Insulation | Units Each Each | Qty 1 1 | Componen Estimated | 1 | | Actual | |

| Measure 11 Atti | c Ins. R-19 | | | Componen | <i>t</i> s A1 | | 1 | nspected |
|---|---|----------------------|----------------|---------------------------|---------------------------------------|--------------------|------------|-----------|
| Comment | | | | | | | | |
| | | | | Estimated | | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | Attic Insulation - Blown Fiberglass - R-19 | SqFt | 775 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | | | Sub Total: | |
| Field Notes: | | | | | | | | |
| Measure 12 Wa | II Insulation | | | Componen | <i>t</i> s E1,N1 | ,S1,W1 | 1 / | nspected |
| | II Insulation | | | Componen Estimated | | ,S1,W ² | 1 Actual | Inspected |
| Measure 12 Wa | II Insulation Description / Comment | Units | Qty | • | | ,S1,W ² | | Inspected |
| Measure 12 Wa Comment # Material / Labor | | <i>Units</i> SqFt | | Estimated | · · · · · · · · · · · · · · · · · · · | | Actual | |
| Measure 12 Wa Comment # Material / Labor | Description / Comment Wall Insulation - Blown | | Qty | Estimated | · · · · · · · · · · · · · · · · · · · | | Actual | |
| Measure 12 Wal Comment # Material / Labor 1 Insulation | Description / Comment Wall Insulation - Blown | | Qty | Estimated | · · · · · · · · · · · · · · · · · · · | | Actual | |
| Measure 12 Wal Comment # Material / Labor 1 Insulation | Description / Comment Wall Insulation - Blown | SqFt | Qty 732 | Estimated | · · · · · · · · · · · · · · · · · · · | Qty | Actual | |

| Measure 13 Flo | oor Ins. R-19 | | | Componen | ts F1 | | | nspected |
|--------------------|---|-------|--------|--------------|-------|-------|------------|-----------|
| Comment | | | | Estimated | | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | Floor Insulation - Fiberglass Batts - R-19 | SqFt | 775 | | | | | |
| Other Detail | | | | | |] [] | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | |] | Sub Total: | |
| | | | | | | | | |
| Manager 44 Da | friends a Bulancat | | | 0 | 4- | | | Inchested |
| | frigerator Rplcmnt ACE W/18CF REFRIGERA | \T∩R | | Componen | ts | | , | nspected |
| Comment IXET E | AGE WITOOT REFRIGERA | VIOIC | | Estimated | | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 10 Refrigerators | - | Each | 1 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | |] ; | Sub Total: | |
| Field Notes: | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

Measure 15 Storm Windows

Components WD10,WD3,WD4,W D9,WD5,WD8,WD1, WD11,WD2,WD6

| Ins | ne | cted | 4 |
|------|----|------|---|
| 1113 | μE | CIEL | 4 |

| Comment | | | | | | | | |
|--|--|----------------------|----------------|---------------------|-------|-----|------------------|----------|
| | | | | Estimated | | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Windows | Storm Window | SqFt | 112 | | | | | |
| 2 Labor | Storm Window | SqFt | 112 | | | | | |
| 3 Other | Storm Window | Each Window | 10 | | | | | |
| Other Detail | | | | | | 7 | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | | ; | Sub Total: | |
| Field Notes: | | | | | | | | |
| | | | | | | | | |
| Measure 16 CO | Monitor is Needed | | | Componen | ts | | - | Inspecte |
| Measure 16 CO Comment | Monitor is Needed | | | - | | | | Inspecte |
| Comment | | | | Estimated | | | Actual | |
| | Monitor is Needed Description / Comment | Units | Qty | - | | Qty | | Inspecte |
| Comment | Description / Comment | <i>Units</i> Each | | Estimated | | Qty | Actual | |
| Comment # Material / Labor 1 Health and Safety | Description / Comment | | Qty | Estimated | | Qty | Actual | |
| Comment # Material / Labor 1 Health and Safety Items | Description / Comment CO monitor | Each | Qty 1 | Estimated | | Qty | Actual | |
| Comment # Material / Labor 1 Health and Safety Items 2 Labor | Description / Comment CO monitor | Each | Qty 1 | Estimated | | Qty | Actual | |
| Comment # Material / Labor 1 Health and Safety Items 2 Labor | Description / Comment CO monitor | Each | Qty 1 | Estimated | | Qty | Actual | |
| Comment # Material / Labor 1 Health and Safety Items 2 Labor | Description / Comment CO monitor | Each Hour | Qty 1 1 | Estimated | | | Actual | |
| Comment # Material / Labor 1 Health and Safety Items 2 Labor | Description / Comment CO monitor | Each Hour | Qty 1 1 | Estimated Unit Cost | | | Actual Unit Cost | |
| # Material / Labor 1 Health and Safety Items 2 Labor Other Detail | Description / Comment CO monitor | Each Hour | Qty 1 1 | Estimated Unit Cost | | | Actual Unit Cost | |
| # Material / Labor 1 Health and Safety Items 2 Labor Other Detail | Description / Comment CO monitor | Each Hour | Qty 1 1 | Estimated Unit Cost | | | Actual Unit Cost | |

| Measure 17 Fix Drip Leg Not Present | | | | Components | | | | Inspected | | |
|-------------------------------------|---|---------------------------------|----------------------|--------------|---------------------|-------|--------|------------------|----------|--|
| C | omment | | | | | | | | | |
| | | | | Estimated | | | Actual | | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| 1 | Health and Safety Items | Drip leg / drain | Each | 1 | | | | | | |
| 2 | Labor | Labor | Hour | 1 | | | | | | |
| C | ther Detail | | | | | | | | | |
| | | | | | | | | | | |
| Ī | | | | | | | | | | |
| | | | | Measur | e Sub Total: | |] ; | Sub Total: | | |
| Ī | Field Notes: | | | | | | | | | |
| | Measure 18 Fix \ | /entilation Inadequate (| (Attic) | | Componen | ts | | | Inspecte | |
| | Measure 18 Fix \ | /entilation Inadequate (| (Attic) | | Componen | | | | Inspecte | |
| С | omment | • | | | Estimated | | 04: | Actual | | |
| C # | omment Material / Labor | Description / Comment | Units | Qty | • | | Qty | | Inspecte | |
| C # | omment | • | | Qty 1 | Estimated | | Qty | Actual | | |
| C # | omment Material / Labor Health and Safety | Description / Comment | Units | | Estimated | | Qty | Actual | | |
| C # 1 | omment Material / Labor Health and Safety Items | Description / Comment Equipment | <i>Units</i> Each | 1 | Estimated | | Qty | Actual | | |
| C # 1 | Material / Labor Health and Safety Items Labor | Description / Comment Equipment | <i>Units</i> Each | 1 | Estimated | | Qty | Actual | | |
| C # 1 | Material / Labor Health and Safety Items Labor | Description / Comment Equipment | <i>Units</i> Each | 1 | Estimated | | Qty | Actual | | |
| C # 1 | Material / Labor Health and Safety Items Labor | Description / Comment Equipment | Units Each Hour | 1 | Estimated | | | Actual | | |
| C # 1 | Material / Labor Health and Safety Items Labor Ather Detail | Description / Comment Equipment | Units Each Hour | 1 | Estimated Unit Cost | | | Actual Unit Cost | | |
| C # 1 | Material / Labor Health and Safety Items Labor | Description / Comment Equipment | Units Each Hour | 1 | Estimated Unit Cost | | | Actual Unit Cost | | |

| Measure 19 Replace Electrical Pig Tail on W Heater | | | on Water | | Componen | ts | Inspected | | | |
|---|-------------------------|--|----------|--------------------|--------------|------------|-----------|------------|-----------|--|
| C | comment Overflow | /Pressure relief pipe | | | | | | | | |
| | | | | Estimated | | Actual | | | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| 1 | Health and Safety Items | Drip leg / drain | Each | 1 | | | | | | |
| 2 | Labor | Labor | Hour | 1 | | | | | | |
| C | Other Detail | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | 1 | Measur | e Sub Total: | | | Sub Total: | | |
| | (Bas | or Barrier Needed ement/CrawIspace) | | | Componen | ts | | | Inspected | |
| C | comment | | | | Estimated | , | | Actual | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| | Health and Safety Items | Basement / crawlspace vapor barrier | Each | 1 | | | | | | |
| 2 | Labor | Labor | Hour | 1 | | | | | | |
| C | Other Detail | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | 1 | Measure Sub Total: | | Sub Total: | | | | |
| | Field Notes: | | | | | | | | | |
| Work Order Grand Total: Grand Total: | | | | | | | | | | |